



TELEPHONE (408) 720-8300
FACSIMILE (408) 720-8383
BSTZ_MAIL@BSTZ.COM
WWW.BSTZ.COM

09/1141535 cjc
BLAKELY SOKOLOFF TAYLOR & ZAFMAN

A LIMITED LIABILITY PARTNERSHIP INCLUDING LAW CORPORATIONS

INTELLECTUAL PROPERTY LAW

SILICON VALLEY

1279 OAKMEAD PARKWAY
SUNNYVALE, CALIFORNIA 94085-4040

RR

OTHER OFFICES

SILICON VALLEY/SAN JOSE, CA
LOS ANGELES, CA
ORANGE COUNTY/COSTA MESA, CA
PORTLAND/LAKE OSWEGO, OR
SEATTLE, WA
DENVER, CO
AUSTIN, TX

November 19, 2003

Assistant Commissioner
of Patents
Washington, D.C. 20231

Certificate

DEC 12 2003

of Correction


Re: **CERTIFICATE OF CORRECTION**
U. S. Letters Patent No. 6,632,704
Issued: Oct. 14, 2003
For: **MOLDED FLIP CHIP PACKAGE**
Inventor: Kumamoto et al.
Our File No. 42390.P9482

Dear Sir:

Enclosed is the Certificate of Correction (two copies) for the above-referenced patent.
This request for correction is made under rule 322 of the Rules of Practice and 35 U.S.C.
Section 254.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP


Edwin H. Taylor
Reg. No. 25,129

EHT/gx
Enclosures

DEC 12 2003

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

DEC 12 2003

PATENT NO. : 6,632,704
DATED : Oct. 14, 2003
INVENTOR(S) : Kumamoto et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 5, line 14, delete "fall", insert --full--.

In column 6, line 5, after "upper inner surface,", insert --the lower mold portion having a lower inner surface, and--.

In column 6, line 8 and 9, delete "between the upper and lower mold portions", insert --that has an upper portion that includes the release film coated on the upper inner surface of the upper mold portion, and a lower inner surface that includes the lower inner surface of the lower mold--.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,632,704

Certificate of Correction (PTO Form 1050)-Amended

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

DEC 12 2003

PATENT NO. : 6,632,704
DATED : Oct. 14, 2003
INVENTOR(S) : Kumamoto et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 5, line 14, delete "fall", insert --full--.

In column 6, line 5, after "upper inner surface,", insert --the lower mold portion having a lower inner surface, and--.

In column 6, line 8 and 9, delete "between the upper and lower mold portions", insert --that has an upper portion that includes the release film coated on the upper inner surface of the upper mold portion, and a lower inner surface that includes the lower inner surface of the lower mold--.

MAILING ADDRESS OF SENDER
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN
12400 Wilshire Blvd. 7th floor
Los Angeles, CA 90025-1026

PATENT NO. 6,632,704

Certificate of Correction (PTO Form 1050)-Amended